

Date 18/12/2018 Gas Safe Register No

3478691




Gas Safe Register  
Licence Number

555555

Serial No 200D Kingston Rd

# Dynamic Gas Solutions Ltd

## LANDLORD/HOMEOWNER GAS SAFETY RECORD

DETAILS OF LANDLORD/HOMEOWNER (or agent where appropriate)		ADDRESS OF THE INSTALLATION	DETAILS OF REGISTERED BUSINESS				
Shirlaw Homes Limited Office Murrills House 48 East Street		200D Kingston Rd Portsmouth	Dynamic Gas Solutions Ltd 78 Hill Rd Fareham Hampshire				
PO16 9XS		PO2 7LR	02392040432		PO16 8JY		
DETAILS OF WORK CARRIED OUT							
Gas safety inspections							
DEFECTS IDENTIFIED			GAS INSTALLATION PIPEWORK				
Warning Notice Issued?			Pipework visual inspection	Outcome of gas supply pipework visual inspection	Is the Emergency Control Valve access satisfactory?	Outcome of gas tightness test?	Is protective equipotential bonding satisfactory?
1			✓	✓	✓	✓	✓
2							
3							
4							
5							
ANY REMEDIAL ACTION TAKEN		Numbers should correspond to defects above					
		<b>Record issued by:</b> Signature  Name (Capitals) S.kerridge Record received by: (tenant/landlord/homeowner/agent) Signature  Name (Capitals) 					
		<div style="border: 2px solid black; padding: 5px; text-align: center;"> <b>ATTENTION</b>            Next safety check due by:  <b>18/12/2019</b> </div>					

This record can be used to document the outcomes of the checks and tests required by The Gas Safety (Installation and Use) Regulations. Some of the outcomes are as a result of visual inspection only and are recorded as appropriate. Unless specifically recorded no detailed inspection of the flue lining, construction or integrity has been performed

APPLIANCE DETAILS								APPLIANCE RESULTS							
Appliance Number	Location	Type	Manufacturer	Model	Owned by Landlord/homeowner?	Inspected Yes/No?	Type of Flue	Operating pressure in mbar &/or heat input kW/h or Btu/h	Operation of safety device(s) Pass/Fail or N/A	Ventilation Satisfactory Yes/No	Visual condition of flue & termination Pass/Fail N/A	Flue operation checks Pass/Fail/N/A	Combustion analyser reading (if applicable)	Serviced Yes/No?	Safe to use Yes/No?

1	Utility	Boiler	Ideal	Logic 24	Yes	Yes	RS	24kw	Pass	Yes	Pass	Pass	0.0004	Yes	✓
---	---------	--------	-------	----------	-----	-----	----	------	------	-----	------	------	--------	-----	---

Audible CO Alarm		
Approved CO alarm fitted?	Is CO alarm In Date?	CO alarm test satisfactory?
Yes		

--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--

Audible CO Alarm		
Approved CO alarm fitted?	Is CO alarm In Date?	CO alarm test satisfactory?

--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--

Audible CO Alarm		
Approved CO alarm fitted?	Is CO alarm In Date?	CO alarm test satisfactory?

--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--

Audible CO Alarm		
Approved CO alarm fitted?	Is CO alarm In Date?	CO alarm test satisfactory?

--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--

Audible CO Alarm		
Approved CO alarm fitted?	Is CO alarm In Date?	CO alarm test satisfactory?